

25X1

5. Harbor [] that depth of water in harbor is sufficient for merchant vessels up to 28° loaded draft. 25X1

25X1

9. New Construction [] no new construction in progress in subject port. 25X1

25X1

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

NO DISSEM ABROAD

LIMITED

C-O-N-F-I-D-E-N-T-I-A-L

- 3 -

11. Shipbuilding and Ship Repair [redacted] a repair yard at designator D. 25X1
The only work in progress in this yard was on trawlers. [redacted]

25X1

12. [redacted] 25X1

13. [redacted]

14. Naval Vessels [redacted] two Soviet SS moored alongside the naval facility at subject port. These boats most closely resembled the "L-1" Class. A flotilla of Soviet DDE, possibly "Riga" and "Kola" class, were moored alongside naval facility. The DDE were both single and two stack vessels. [redacted] 25X1

25X1

25X1

- end -

25X1

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

NO DISSEM ABROAD

LIMITED

Approved For Release 2009/01/14 : CIA-RDP80-00926A008400880001-7


25X1

Page Denied

Approved For Release 2009/01/14 : CIA-RDP80-00926A008400880001-7

Berth at Designator A Alongside Stone Quay

Quay is served by seven
diesel-powered cranes of
approximately 5-ton capacity



25X1

WINDAU RIVER

Figure 8-a

Plan View
Ventpils, U.S.S.R.

CONFIDENTIAL

Berth at Designator B




Figure 8-b

Plan View
Ventapils, U.S.S.R.

CONFIDENTIAL

JA)

NOTE ON SOUNDINGS
The water level as Libras is reported to fall from 2 to 4 feet below the level to which the soundings have been reduced.

All Bearings are True (thus 126° etc.) and are given from Seaward

NOTE

SOUNDINGS IN FEET
Reduced approximately to Mean Sea Level 190.42

25X1

scale in the area
within 8 miles
to be 22 ft. in 1922,
and, when near the
low water.

